

Quality is the indispensable component
of every Simpson instrument

OBSOLETE
Simpson

INSTRUMENTS THAT STAY ACCURATE

OPERATOR'S MANUAL

WARNING

For safe usage, it is essential that the operator
read this manual carefully before using the
instrument for any measurements.

MODEL 460 SERIES 3
DIGITAL MULTIMETER

SIMPSON ELECTRIC COMPANY

851 Beulah Ave., Elgin, Illinois 60120

Area Code 312, Telephone 990-2100

In Canada, Bach-Simpson, Ltd., London, Ontario

DIGITAL INSTRUMENT

Warranty

SIMPSON ELECTRIC COMPANY warrants each digital instrument manufactured by it to be free from defects in material and workmanship under normal use and service, its obligation under this warranty being limited to making good at its factory any digital instrument which shall within one (1) year after delivery of such instrument or other article of equipment to the original purchaser be returned intact to it, or to one of its authorized service stations, with transportation charges prepaid, and which its examination shall disclose to its satisfaction to have been free from defective; this warranty being expressly in lieu of all other warranties expressed or implied and of all other obligations or liabilities on its part, and SIMPSON ELECTRIC COMPANY neither assumes nor authorizes any other person to assume for it any other liability in connection with the sale of its products.

This warranty shall not apply to any digital instrument which shall have been repaired or altered outside the SIMPSON ELECTRIC COMPANY factory or authorized service stations, nor which has been subject to misuse, negligence or accident, incorrect wiring by others, or installation or use not in accord with instructions furnished by the manufacturer.



SIMPSON COMPANY

855 Dundas Ave. E., Dept. 800-120

Phone (416) 291-2200

IN CANADA: Radio Shack, Inc., Toronto, Ontario

IN BRITAIN: Radio Shack (UK) Limited, Watlington, Oxford

IN INDIA: Radio Shack (India) Private Ltd., Hyderabad, Andhra Pradesh

IN AUSTRALIA: Radio Shack (Australia) Pty. Ltd., Sydney



OBSOLETE

OPERATOR'S MANUAL

SIMPSON 460 SERIES 3 DIGITAL MULTIMETER

SIMPSON ELECTRIC COMPANY

855 Dundas Ave. E., Dept. 800-120

Area Code 416, Telephone 892-2200

In Canada, Radio Shack, Ltd., London, Ontario

Printed in U.S.A.
SIMPSON 460-3

Part No. S-718871



Figure 1-1. Digital Multimeter, 400-2

TABLE OF CONTENTS

OBsolete

SECTION I	
Introduction	1-1
1.1 General	1-1
1.2 Accessories and Supplies	1-2
1.3 Technical Data	1-3
1.4 Safety Considerations	1-3
SECTION II	
Installation	2-0
2.1 General	2-0
2.2 Unpacking and Inspection	2-1
2.3 Power Source Requirements	2-1
2.4 Warranty	2-2
2.5 Shipping	2-2
2.6 Installation	2-2
SECTION III	
Controls, Connectors and Indicators	3-1
3.1 General	3-1
3.2 Front and Rear Panel Descriptions	3-1
SECTION IV	
Operation	4-0
4.1 General	4-0
4.2 Safety Precautions	4-0
4.3 Preliminary Notes and Checks	4-2
4.4 General Functional Checks	4-3
4.5 DC Voltage Measurements	4-3
4.6 AC Voltage Measurements	4-3
4.7 Resistance Measurements	4-3
4.8 DC Current Measurements	4-3
4.9 AC Current Measurements	4-3B
SECTION V	
Theory of Operation	4-11
5.1 General	4-11
5.2 Overall System	4-11
5.3 Input Circuits	5-2
5.4 A/D Converter	5-3
5.5 Power Supply Circuits	5-3

SECTION VI

Service Instructions	6-1
6.1 General	6-1
6.2 Carry Reserve	6-1
6.3 Battery Installation (auto-only)	6-2
6.4 Battery Charging (auto-only)	6-2
6.5 Battery Care	6-3
6.6 Fuse Replacement	6-3
6.7 Preventive Maintenance	6-4
6.8 Troubleshooting	6-5

SECTION VII

Replacement Parts, Schematic Diagram, and Authorized Service Centers	7-1
7.1 General	7-1

LIST OF TABLES

1-1 Technical Data	1-2
1-2 Accessories and Items Furnished with this Instrument	1-8
2-1 Front and Rear Panel Descriptions	2-1
4-1 DC Voltage Ranges and Connections	4-5
4-2 AC Voltage Ranges and Connections	4-6
4-3 Resistance Ranges and Connections	4-7
4-4 DC Current Ranges and Connections	4-9
4-5 AC Current Ranges and Connections	4-10
6-1 Troubleshooting Chart	6-6
7-1 Replacement Parts List	7-1

LIST OF ILLUSTRATIONS

1-1 Digital Multimeter, 400-3	1
2-1 Front Panel Description	2-1
2-2 Rear Panel Description	2-2
3-1 Battery System Block Diagram, 400-3	3-1
3-2 Battery Voltage Measurement Circuit	3-2
3-3 Battery DC Current and Resistance Measurement Circuit	3-3
3-4 Auto Converter Block Diagram	3-7
3-5 Pulse Timing Diagram	3-8
3-6 Fuse Location, 400-3	3-8
7-1 Schematic Diagram, 400-3	7-6

OBsolete
WARNING

This instrument is designed to prevent accidental shock to the operator when properly used. However, no engineering design can render safe an instrument which is used carelessly. Therefore, this manual must be read carefully and completely before making any measurements. Failure to follow directions can result in a serious or fatal accident.

SHOCK HAZARD: As defined in American National Standard, ANSI Safety Requirements for Electrical & Electronic Measuring & Controlling Instrumentation, a shock hazard shall be considered to exist if any part involving a potential in excess of 30 volts rms (sine wave) or 42.4 volts DC or peak and where a leakage current from that part to ground exceeds 0.5 milliamperes, when measured with an appropriate measuring instrument defined in Section 1.1.6.1 of ANSI C80.1.

NOTE: The proper measuring instrument for the measurement of leakage current consists essentially of a network of a 1500 ohm non-inductive resistor also rated by a 0.15 microfarad capacitor connected between the terminals of the measuring instrument. The leakage current is that portion of the current that flows through the resistor. The Simpson Model 229-Series 2 AC Leakage Current Tester meets the ANSI C80.1 requirements for the measurement of AC leakage current and can be used for this purpose. To measure DC leakage current, connect a 1500 ohm non-inductive resistor in series with a Simpson 6-808 DC microammeter and use this as the measuring instrument.

SECTION I INTRODUCTION

1.1 GENERAL

1.1.1 The Simpson 468 Series 3 Digital Multimeter is a versatile 3½ digit instrument, available for use in general electronic maintenance, production, and laboratory. It features 0.1% DCV accuracy, integrated circuit electronics, solid-state LED display, and pushbutton switch selection for ranges and functions. Additional features are automatic polarity, analog indication, separate "low" and "high" power resistance ranges, and excellent temperature and over-ranging characteristics.

1.1.2 The 468-3 is available in two versions: the 468A is a standard instrument designed to operate from a 115 or 240 volts AC (50-400 Hz) power source (check rear panel designation). The 468D is an optional version designed for either AC line operation or battery operation using rechargeable nickel-cadmium cells. The battery can operate the instrument for eight hours continuously. Recharging is automatic when the instrument is in the OFF position and with the line cord connected to an AC power source. Hereafter, all information and data applies to both instruments (referred to as the 468, or the instrument).

1.1.3 The 468 (Figure 1-1) measures DC and AC voltage, DC and AC current and resistance as specified in Table 1-1. The up-down integration technique is used for the analog-to-digital (A/D) conversion because of its inherently excellent stability, accuracy, and noise immunity. The use of a Simpson custom CMOS-LSI integrated circuit achieves high reliability, low power dissipation, and a compact design.

1.1.4 The numerical display is a 7-segment light-emitting-diode (LED) display for easy viewing and solid state reliability. The numerals are .043 inch high and in a single plane for direct and wide-angle viewing. Ambient lighting effects are

minimized

minimized by a filter which reduces reflections and background illumination.

1.1.5 The analog meter provides quick and convenient indications for nulling, peaking, scanning and varying signal applications. Both linear and decibel (dB) scales are on the analog display.

1.2 ACCESSORIES AND SUPPLIES

1.2.1 All supplies and accessories required for the operation of the 468 (using powerline) are furnished with the instrument and listed in Table 2-1. Batteries for the 468D are not supplied. Available replacement parts are listed in Table 2-1.

1.3 TECHNICAL DATA

1.3.1 Table 1-1 lists the technical data for the 468.

Table 1-1. Technical Data

1.3C VOLTAGE:

Range	Maximum Indication	Input Resistance	Overload Protected To
200 mV	±200.0 mV	20 MΩ	±1100 V
2V	±2,000 V	20 MΩ	±1100 V
20 V	±20,000 V	20 MΩ	±1100 V
200 V	±200,000 V	20 MΩ	±1100 V
1000 V	±2000 V	20 MΩ	±1100 V

(Max. Input)

Accuracy (from -10°C to +30°C)

±0.1% of reading + 1 digit

Input Bias Current:

50pA at reference conditions

Sensitivity:

200µV on 200 mV range

Full Range Delay Response (to rated accuracy)

1 second

OBSOLETE

Introduction

Normal Mode

Rejection: 60 dB minimum at 60 Hz

Common Mode

Rejection: 90 dB minimum at 60 Hz with 1,000 Ω imbalance

Overrange Capability:

Linear to 1000 counts beyond maximum indication (except on 1000 V range, where any indication greater than 999 is an overload).

Temperature

Coefficient (from 0°C to +50°C):

$\pm(0.07\%$ of reading $+ 0.1$ digit/°C)

B. AC VOLTAGE:

(Average Sensing, RMS Calibrated Sine Wave, 40 Hz to 20 kHz)

Range	Maximum Indication	Input Impedance	Overload Protected To
200 mV	199.9 mV	20 M Ω and 75 pF	200 V RMS
1 V	1,999 V	20 M Ω and 75 pF	200 V RMS
20 V	19,99 V	20 M Ω and 75 pF	200 V RMS
200 V	199.9 V	20 M Ω and 75 pF	200 V RMS
600 V	599 V	20 M Ω and 75 pF	200 V RMS

(Max. Input)

Accuracy (from +15°C to +35°C):

$\pm(0.5\%$ of reading $+ 1$ digit), 40 Hz to 10 kHz, except 600 V range, which is 40 Hz to 400 Hz

$\pm(1.0\%$ of reading $+ 1$ digit), 10 kHz to 20 kHz, except 600 V range, which is 400 Hz to 20 kHz

Sensitivity:

100 μ V on 200 mV range

Full Range Step

Response (to rated accuracy):

1 second

Introduction

Overrange Capability:

Linear to 999 counts beyond maximum indication (except on 600 V range, where any indication greater than 999 is an overload).

Temperature

Coefficient (from 0°C to +50°C):

$\pm(0.05\%$ of reading $+ 0.1$ digit/°C)

B. RESISTANCE:

A. LC OHMS (Maximum Open-Circuit Voltage = 7V)

Range	Maximum Indication	Full Scale Voltage	Test Current	Overload Protected To
200 Ω	199.9 Ω	200 mV	1 mA	100 V RMS
1 k Ω	1,999 k Ω	200 mV	100 μ A	100 V RMS
20 k Ω	19,999 k Ω	200 mV	10 μ A	200 V RMS
200 k Ω	199.9 k Ω	200 mV	1 μ A	200 V RMS
2000 k Ω	9999 k Ω	200 mV	100 nA	200 V RMS

B. HI OHMS

Range	Maximum Indication	Full Scale Voltage	Test Current	Overload Protected To
1 M Ω	1,999 k Ω	2 V	1 mA	100 V RMS
20 k Ω	19,999 k Ω	2 V	100 μ A	200 V RMS
200 k Ω	999.9 k Ω	2 V	10 μ A	200 V RMS
2000 k Ω	9999 k Ω	2 V	1 μ A	200 V RMS
20 M Ω	19,999 M Ω	2 V	100 nA	200 V RMS

Accuracy (from +15°C to +35°C):

$\pm(0.5\%$ of reading $+ 1$ digit) except on the 2000 k Ω and 20 M Ω ranges, which are $\pm(0.5\%$ of reading $+ 1$ digit)

Sensitivity:

0.1 Ω on 200 Ω range

Full Range Step

Response (to rated accuracy):

1 second, except on 20 M Ω range, which is 10 seconds

OBSOLETE

Full Range Step Response
(Rated accuracy)

1 second

Temperature Coefficient
(from 0°C to +55°C)

±(0.01% of reading + 0.1 digit)/°C

Overrange Capability:

Linear to 500 counts beyond maximum indication (except on 10A range, where any indication greater than 1000 is an overload).

4. DC CURRENT:

Range	Maximum Indication	Full Range Voltage Drop	Overload Protected To
200 μ A	±199.9 μ A	300 mV	±1.5 A ¹
2 mA	±1.999 mA	300 mV	±1.5 A ¹
20 mA	±19.99 mA	300 mV	±1.5 A ¹
200 mA	±199.9 mA	300 mV	±1.5 A ¹
2000 mA	±1999 mA	300 mV	±1.5 A ¹
10 A	±19.99 A	300 mV	±10 A (50 V Max.)

Fuse Protected

Accuracy (from +15°C to +55°C): ±(0.15% of reading + 1 digit), except on 2000mA and 10A ranges, which are ±(1.0% of reading + 1 digit)

Sensitivity: 200 μ A on 200 μ A range

Full Range Step Response (Rated accuracy)

1 second

Temperature Coefficient (from 0°C to +55°C)

±(0.01% of reading + 0.1 digit)/°C

Overrange Capability:

Linear to 500 counts beyond maximum indication (except on 10 A range, where any indication greater than 1000 is an overload).

5. AC CURRENT (40 Hz to 50 kHz)

Range	Maximum Indication	Full Range Voltage Drop	Overload Protected To
200 μ A	199.9 μ A	300 mV	±1.5 A ¹
2 mA	1.999 mA	300 mV	±1.5 A ¹
20 mA	19.99 mA	300 mV	±1.5 A ¹
200 mA	199.9 mA	300 mV	±1.5 A ¹
2000 mA	1999 mA	300 mV	±1.5 A ¹
10 A	19.99 A	300 mV	10A (50 V Max.)

Fuse Protected

Accuracy (from +15°C to +55°C): ±(0.1% of reading + 1 digit), except on 2000 mA and 10A ranges, which are ±(1.0% of reading + 1 digit)

Sensitivity: 100 μ A on 200 μ A range

Full Range Step Response (Rated accuracy)

5 seconds

Temperature Coefficient (from 0°C to +55°C)

±(0.01% of reading + 0.1 digit)/°C

Overrange Capability:

Linear to 500 counts beyond maximum indication (except on 10A range, where any indication greater than 1000 is an overload)

6. RATED CIRCUIT-TO-GROUND VOLTAGE:



(Maximum Common Mode Input Voltage):

1000 volts (DC plus peak AC) maximum from any measuring terminal to ground line (earth) ground terminal, except on 10A range, which is 50 volts maximum.

¹The ANSI C-39.5-1974: The specified voltage with respect to ground which may be safely and continuously applied to the circuits of an instrument.

OBSOLETE

Introduction**7. RESOLUTION:**

1 part in 2000

8. DISPLAY:

- Numerical Display: 2-1/2 digit, 7 segment light-emitting diode (LED) type, with 0.40 inch high numerals.
- Conversion Rate: 4 readings per second, nominal.
- DC Polarity Selection: Automatic with "+" or "-" indication.
- Overrange Indication: Automatic beyond 1999, with the "1" digit blinking.
- Analog Display: 0-10 inch edge-wise meter with both linear and dB scale markings.

9. POWER REQUIREMENT:

- AC Operating (400A) or Battery Charging (400C): 120 VAC or 100 VAC $\pm 10\%$ (check case panel designation), 50-600 Hz, 3 VA nominal. (8 VA for Model 400C).
- Battery Operation (400C): Four nickel-cadmium "D" size rechargeable cells, Eveready type C26 or equivalent (each cell is rated at 1.25E, 4-ampere-hours).
- Battery Operation Time (continuous with fully charged battery): 8 hours, nominal.
- Battery Recharge Time: 16 hours, nominal.

10. TEMPERATURE RANGE:

- Operating: 0°C to +50°C
- Storage: -40°C to +60°C

11. REFERENCE CONDITIONS:

- Temperature: +20°C $\pm 1^\circ\text{C}$
- Relative Humidity: 50 to 80%
- Atmospheric Pressure: 875 to 900 mmHg


Introduction**12. DIMENSIONS:**

- Height: 2.75 in. (70.15mm)
- Width: 6.60 in. (167.64mm)
- Depth: 9.00 in. (228.60mm)

13. WEIGHT:Approximately 2 lbs. (1.00 kg)
(without battery)**Table 1-1. Items Furnished with This Instrument**

Quantity	Description	Part No.
1	Test Lead Set: One black and one red insulated lead, 10-000000 having probe tips with protection for screw-on alligator clips (one red and one black supplied).	
1	Power Card	5-118908
1	Operator's Manual	5-118911

1.4 SAFETY CONSIDERATIONS

1.4.1 This operator's manual contains cautions and warnings alerting the user to hazardous operating and maintenance conditions. This information is flagged by a **CAUTION** or **WARNING** heading and/or the symbol . The symbol appears on the front panel and at certain paragraphs in this manual, and is an international symbol meaning: "refer to the operating or service sections of the Operator's Manual." To ensure the safety of the operating and maintenance personnel and to retain the operating condition of the instrument, these instructions must be adhered to.

OBSOLETE

SECTION II

INSTALLATION

2.1 GENERAL

2.1.1 This section contains information and instructions for the installation and shipping of the Simpson 400. Included are unpacking and inspection procedures, warranty, shipping, power source requirements, and installation.

2.2 UNPACKING AND INSPECTION

2.2.1 Unpack and inspect the instrument for possible damage in shipment. Check the electrical performance as soon as possible. If damage is noted, notify the carrier and supplier before using the instrument. Also check that all items are included (Table 1-2).

2.2.2 Save the shipping carton and packing materials for future storing or shipping of the instrument.

2.3 POWER SOURCE REQUIREMENTS

2.3.1 The 400A is designed to be operated from the AC line only. The 400D is designed to be operated from either the AC line or self-contained nickel-cadmium cells (not furnished with the instrument but available from any local electronic parts distributor. Refer to Table 1-1, Item 9).

2.3.2 AC Line Operation

2.3.2.1 The 400 is wired at the factory for 120 VAC (50 to 60 Hz) operation. To convert your instrument for 240 VAC operation, consult your nearest Simpson Authorized Service Center.



For AC line operation, ensure that the grounding pin of the power plug is securely connected to an earth (grounding) ground. Use a 3-wire grounded outlet which conforms to the latest National Electrical Code.

2.3.4 Battery Operation (400D)

2.3.5 Battery operation is automatic whenever cells are installed, the line cord is disconnected, and one of the FUNCTION switches set to a position other than the POWER-OFF position.

2.3.6 For battery installation and battery test refer to paragraph 6.5.

2.4 WARRANTY

2.4.1 The Simpson Electric Company warranty policy is printed on the inside front cover of this manual. Read it carefully prior to requesting a warranty repair.

NOTE: For assistance of any kind, including help with the instrument under warranty, contact your nearest Authorized Service Center for instructions (listed on the last pages of this manual). If you wish to contact the factory directly, give full details of the difficulty and include the instrument model number, serial number (at the back of the instrument) and date of purchase. Service data or shipping instructions will be sent to you promptly. If an estimate of charges for non-warranty or other service work is required, a maximum charge estimate will be quoted. This charge will not be exceeded without your prior approval.

2.5 SHIPPING

2.5.1 Pack the instrument carefully and ship it prepaid to the proper destination. Insure the instrument.

3.6 INSTALLATION

3.6.1 The instrument may be set horizontally on its four rubber feet or vertically on its back and operated in either position. The instrument can also be set at an inclined angle by positioning the 8-position carrying handle under the unit. To set the instrument at a desirable viewing angle, use the following procedure:

- Pull out both knobs on sides of instrument.
- Rotate handle to one of eight positions.
- Push both knobs into a locking position.

CONTROLS, CONNECTORS AND INDICATORS

3.1 GENERAL

3.1.1 All operating and adjusting controls, connectors and indicators are described in Table 3-1. Become familiar with each item prior to operating the instrument for the first time.

3.2 FRONT AND REAR PANEL DESCRIPTION

3.2.1 Table 3-1 lists all front and rear panel controls, connectors and indicators (Figure 3-1 and 3-2).

Table 3-1. Front and Rear Panel Description

1. POWER Switch:

ON	Applies primary power to the instrument.
OFF	Disconnects primary power from all circuits except the battery charging circuit.

2. FUNCTION Switches:

Position	
AC	Connects the COMMON and mA jacks to the AC current measuring circuits.
AC	Connects COMMON and V- Ω jacks to the AC voltage measuring circuits.
DC	Connects the COMMON and mA jacks to the DC current measuring circuits. Also used when measuring IR drops.
DC	Connects COMMON and V- Ω jacks to the DC voltage measuring circuits.

Controls, Connectors, and Indicators

- 1E OHMS**
[RES] Connects the COMMON and V-Ω jacks to the standard power resistance measuring circuits.
- 1D OHMS**
[RES] Connects the COMMON and V-Ω jacks to the "low power" resistance measuring circuits.

3. RANGE Switches

Position

200 mV

μA

Ω

Selects the circuits required for full range measurements of 0 to ±200mV DC, 0 to 200 mV AC, 0 to ±200 μA DC, 0 to 200 μA AC, 0 to 200 ohms, depending on the function switch selected.

1, 2K, 10A, 20K, 200K

5000 VDC

500 VAC

Selects the circuits required for full range measurements of 0 to the corresponding numerical values of AC mA, rDC mA, Ω, ±DC V or AC V depending on the function switch selected.

20 MΩ

Selects the circuits required for the full range measurement of resistance from 0 to 20 MΩ when the function switch 1E OHMS (RES) is selected.



Refer to Table 1-1, Item 3.

5. H-Ω Jack:

This terminal is used to connect the "high" side of the circuit being measured to all voltage and resistance measuring circuits through the FUNCTION and RANGE switches.

6. COMMON Jack:

This jack is used to connect the "low" side of the circuit measured to the internal circuit COMMON and is isolated from the AC power line ground.

Controls, Connectors, and Indicators



Figure 3-1. Front Panel Description

OBSOLETE



Figure 3-2. Rear Panel Description

Controls, Connectors, and Indicators

3. mA Jack: This terminal is used to connect the "high" side of the current being measured to the current measuring circuit through the FUNCTION and RANGE switches. The "low" side is connected to the COMMON jack.

4. 10A Jack: This terminal is used to connect the "high" side of the 10 ampere full scale current being measured to the current measuring circuit when RANGE switch is 10 (10A) and FUNCTION switch DC mA or AC mA is selected. The "low" side is connected to the COMMON jack.

**5. BATTERY TEST
4.7-6V
(Model 4800 only)** This jack connects to the positive terminal of the battery installed. For battery test, connect a test lead between the V- Ω jack and the BATTERY TEST jack, with the FUNCTION switch DCV and the RANGE switch 10 (10A) selected. The numerical display must indicate a voltage between +4.7 volts and +6.0 volts for proper operation. If the display indicates greater than +6.0 volts, either the battery is not installed or the battery is not installed properly.

10. Numerical Display: The digital display uses LEDs and includes a polarity (+, -) sign, a "1" sign, three 7-segment type 0 to 9 digits and a decimal point, to indicate the polarity and the value of the signal being measured. The decimal point is properly positioned by the selection of the range switch. Over-range (or out-of-range) condition is indicated by a flashing "1" display for 2000 counts or greater.

Controls, Connectors, and Indicators

11. Analog Display: The analog meter displays in analog form the relative value of the input signal being measured. The reading is determined in conjunction with the position setting of the range switch. Two scale markings are provided: a linear scale and a decibel scale marked -20 dB to +2 dB. The dB readings are referenced to a dB power level of 1 milliwatt into a 600 Ω load (an actual voltage of 0.177V). The actual decibel value is determined by:

- (1) Reading the dB scale value, and
- (2) adding the appropriate range factor as follows:

Range	Add
200mV	-20 dB
2 V	0 dB
20 V	+20 dB
200 V	+40 dB
600 V	+60 dB

**12. AC Power
Receptacle:**

This receptacle accepts the AC line power cord used for AC operation or battery charging.

OBSOLETE

SECTION IV

OPERATION

4.1 GENERAL

WARNING

The Simpson 460 is designed to prevent accidental shock when properly used. However, no engineering design can render safe an instrument which is used carelessly. Therefore, this manual must be read completely prior to making any measurements. Failure to do so can result in a serious or fatal accident.

4.1.1 This section of the manual contains information required to use and operate the 460-3 in a safe and proper manner.

4.2 SAFETY PRECAUTIONS

4.2.1 The 460 is designed to be used only by personnel qualified to recognize shock hazards and trained in the safety precautions required to avoid possible injury. Refer to **SHOCK HAZARD** definition on page 7.

4.2.2 Do not work alone when making measurements where a shock hazard can exist. Notify another person nearby that you are or intend to make such measurements.

REMEMBER: Voltage might appear unexpectedly in defective equipment. An open bleeder resistor can result in a capacitor's retaining a dangerous charge. Remove all power and discharge all capacitors in the circuit being measured and remove all power from the 460 before making connections or disconnections.

4.2.3 Locate all voltage sources and accessibility paths prior to making any measurements or connections.

4.2.4 For your own safety, before each use, inspect the test leads, probe, connectors and power cable for cracks, breaks or causes in the insulation. If any defects exist, destroy and replace the defective item(s) immediately.

4.2.5 Do not make measurements in areas where high voltage is present. Corona can be identified by a pale-blue color resulting from sharp metal points in the circuit or a buzzing sound, or the odor of ozone. In rare instances, such as around germicidal lamps, ozone might be generated as a normal function. Ordinarily, the presence of ozone indicates the presence of high voltage, and probably a malfunction of some kind.

4.2.6 Hands, shoes, floor and workbench must be dry. Avoid making measurements under humid, damp, or other environmental conditions that could affect the dielectric withstanding voltage of the test leads or the instrument.

4.2.7 For maximum safety, do not touch test leads, circuit, or instrument while power is applied to the circuit being measured.

4.2.8 Use extreme caution when making measurements in an r-f circuit where dangerous composite voltages could be present, such as in an r-f amplifier.

4.2.9 Do not use test leads which differ from those originally furnished with the instrument.

4.2.10 Before the instrument is used for AC operation, make sure that the "third wire" on the AC power cord is connected to an earth or powerline ground.

4.2.11 Do not float any measuring terminal more than the rated circuit to ground voltage as specified in Table 1-1, item 5.

4.3 PRELIMINARY NOTES AND CHECKS

NOTE: Prior to operation of the instrument, review and perform (where applicable) the following notes and checks. These steps can be used also as a general functional check.

4.3.1 For AC Line Operation

- Ensure that the power source used matches the requirements of the instrument as marked on rear panel.
- Insert the plug into a 3-wire power outlet which conforms to the latest National Electrical Code. The 480D will operate with or without battery power. When the 480D is operating on the AC line with the internal battery installed, the battery is being "trickle" charged.

4.3.2 For 480D battery operation follow this procedure:

OBSOLETE

CAUTION

Do not operate the instrument with cells in the completely discharged state, which is common for all new cells as acquired from the vendor. See paragraph 6.6.

- Disconnect the AC line cord and set the POWER switch to the OFF position. Install four "D" size nickel-cadmium cells (not supplied with instrument). Observe polarity as shown on label inside battery holder. Re-assemble case and turn power ON.
- Depress the DCV function and 20 (10A) range switches.
- Connect a test lead between the V-Ω jacks and the BATTERY TEST jack. The reading must be between +4.7 volts, or if the display does not *emit* light, either the battery is improperly installed or recharging is required.
- If the battery voltage is below +4.7 volts, or if the display does not *emit* light, either the battery is improperly installed or recharging is required.

4.3.3 To recharge the battery, follow this procedure:

- Set the POWER switch to the OFF position. Connect the line cord plug into a 3-wire power outlet which conforms to the power requirements of the instrument as marked on the rear panel, and to the latest National Electrical Code.

- The battery is being charged at full rate ($I = 400mA$).

NOTE: If the battery test indicates a voltage below +4.7 volts, set the POWER switch in the OFF position for at least 15 minutes before operating.

4.4 GENERAL FUNCTIONAL CHECK

- Review the safety precautions in paragraph 4.2.
- Connect the black test lead to the COMMON jack and the red test lead to the V-Ω jack. Short the test leads together.
- Depress and set the HORMAS function and "D" range switches.
- Open the test leads. The numerical display will be flashing in the out-of-range condition.
- Short the test leads together. The display reading will return to 000 ±1 digit.
- If difficulty is encountered in the above steps, see Section VI.

4.5 DC VOLTAGE MEASUREMENTS

- Review the safety precautions in paragraph 4.2.
- Connect input test leads to the V-Ω and COMMON terminals.
- Depress DCV function switch.
- Depress the appropriate voltage range switch as indicated in Table 4-1. If the voltage being measured is unknown, begin with the 1000 range VDC switch.
- Turn off the power to the device or circuit under test and discharge all capacitors.
- Connect test leads to the circuit being measured.
- Apply power to the circuit being measured. The instrument will automatically indicate the correct polarity. The value of the voltage being measured will be indicated on the numerical display. The analog display will indicate the relative value and can be used for nulling or peaking applications.
- Remove all power from the circuit being measured and discharge all capacitors prior to disconnecting test leads.

Operation

- E. Open the circuit in which the current is to be measured and accurately connect the test leads in series. Ensure that the 480-3 is not connected across a voltage source which can exceed ratings of the instrument.

Table 4-1. DC Voltage Range and Connections

Range	Range Switch	Function Switch	Input Connections	Max. Voltage	Remarks
0 to 0.250mV	500 mV	DCV	V-EL, COMMON	±1100V	Auto-Polarity on all ranges
0 to ±2 V	2	DCV	V-EL, COMMON	±1100V	
0 to ±20V	20	DCV	V-EL, COMMON	±1100V	
0 to 0.250V	500	DCV	V-EL, COMMON	±1100V	
0 to ±1000V	5000 VDC	DCV	V-EL, COMMON	±1100V	

Table 4-2. AC Voltage Range and Connections

Range	Range Switch	Function Switch	Input Connections	Max. Voltage	Remarks
0 to 500mV	500mV	ACV	V-EL, COMMON	150V RMS	40 Hz-20 kHz on all ranges
0 to 2V	2	ACV	V-EL, COMMON	150V RMS	
0 to 20V	20	ACV	V-EL, COMMON	150V RMS	
0 to 500V	500	ACV	V-EL, COMMON	650V RMS	
0 to 500V	500 VAC	ACV	V-EL, COMMON	650V RMS	

Operation

4.6 AC VOLTAGE MEASUREMENT

- Review safety precautions in paragraph 4.2.
- Connect input test leads to the V-EL and COMMON terminals.
- Depress the ACV function switch.
- Depress the appropriate voltage range switch as indicated in Table 4-2. If the voltage being measured is unknown, begin with the 500 range VAC switch.

CAUTION OBSOLETE

Do not attempt to measure voltages on the 500 VAC range which might be greater than 550 volts.

- Remove all power from the circuit being measured and discharge all capacitors.
- Connect test leads to the circuit being measured.
- Apply power to the circuit being measured. The value of the voltage being measured will be indicated on the numerical display. The analog display can be used for reading or peaking applications.
- Remove all power from the circuit being measured and discharge all capacitors prior to disconnecting test leads.

4.7 RESISTANCE MEASUREMENTS

4.7.1 GENERAL

The 480 measures resistance from 0.01 to 20 MΩ in two overlapping modes — LO OHMS and HI OHMS. The LO OHMS mode is useful for measurements which require low power dissipation, low voltage drop (200mV F.S.) across the resistance, and low open-circuit voltage (less than 1 volt). These features are especially desirable for in-circuit resistance measurements which require non-conduction of semiconductor junctions. The low open-circuit voltage in the LO OHMS mode eliminates the possibility of damaging certain semiconductor junctions. The HI OHMS is useful for measurements which require a higher

Operation

voltage across the resistance, such as testing conductors in transformers and diodes.

4.7.2 MEASUREMENT PROCEDURE

- Review the Preliminary Notes and Checks in paragraph 4.3.
- Connect input test leads to the V-Ω and COMMON terminals.
- Depress either the HI OHMS or the LO OHMS function switch.
- Depress the appropriate resistance range switch as indicated in Table 4-3.
- If the resistance being measured is connected into a circuit, be certain that all power is removed from the circuit and all capacitors are discharged. Check for current paths other than through the resistance being measured. These paths can result in a measured value which is lower than the actual value of the resistance being measured.

OBSOLETE

Table 4-3. Resistance Ranges and Connections

A. LO OHMS (Maximum Open-Circuit Voltage = 1V)

Range	Range Switch	Function Switch	Input Connections	Test Current	Full Scale Voltage
0 to 2000	2000	LO-OHMS	V-Ω, COMMON	1mA	200mV
0 to 200	2	LO-OHMS	V-Ω, COMMON	100µA	200mV
0 to 20kΩ	20	LO-OHMS	V-Ω, COMMON	10µA	200mV
0 to 200kΩ	200	LO-OHMS	V-Ω, COMMON	1µA	200mV
0 to 2000kΩ	2000	LO-OHMS	V-Ω, COMMON	100nA	200mV

Operation

OBSOLETE

B. HI OHMS

Range	Range Switch	Function Switch	Input Connections	Test Current	Full Scale Voltage
0 to 20k	2	HI-OHMS	V-Ω, COMMON	1mA	2V
0 to 20kΩ	20	HI-OHMS	V-Ω-COMMON	100µA	2V
0 to 200k	200	HI-OHMS	V-Ω, COMMON	10µA	2V
0 to 2000kΩ	2000	HI-OHMS	V-Ω, COMMON	1µA	2V
0 to 200k	200k	HI-OHMS	V-Ω, COMMON	100nA	2V

- Connect the test leads to the resistance being measured. Be careful not to contact adjacent points, even if insulated, particularly when making high resistance measurements. Some insulators can have relatively low insulation resistances, which can sufficiently shunt the resistance being measured to result in a measured value lower than the presented value.

NOTE: If the resistance being measured is polarity or voltage sensitive (for example, semiconductors), careful considerations must be given when making connections and selecting the resistance range (refer to Table 4-3).

- Allow time for the display to stabilize. This procedure is especially important when measuring a high value resistance shunted by a large value of capacitance.
- Disconnect test leads.

4.8 DC CURRENT MEASUREMENTS

- Review Safety Precautions in paragraph 4.2.
- Depress the DC mA function switch.

Operation

- Depress the appropriate current range switch as indicated in Table 4-4. If the current being measured is unknown (but less than 10A), begin with the 20(10A) switch. Connect the red test lead to the 10A jack and the black test lead to the COMMON jack.
- Remove all power to the circuit being measured and discharge all capacitors.
- Connect the test leads according to Table 4-4.

Table 4-4. DC Current Ranges and Connections

Range	Range Switch	Function Switch	Input Connections	Max. Current Amperes	Remarks
0 to $\pm 200\mu\text{A}$	200 μA	DCmA	mA, COMMON	± 2.5	<p>Acute Polarity on all ranges</p>
0 to $\pm 2\text{mA}$	2	DCmA	mA, COMMON	± 2.5	
0 to $\pm 20\text{mA}$	20mA	DCmA	mA, COMMON	± 2.5	
0 to $\pm 200\text{mA}$	200	DCmA	mA, COMMON	± 2.5	
0 to $\pm 2000\text{mA}$	2000	DCmA	mA, COMMON	± 2.5	
0 to $\pm 10\text{A}$	10 10A	DCmA	10A, COMMON	± 10	

- Open the circuit to be measured and securely connect the instrument. Be sure that the Model 880-3 is not connected across a voltage source which can exceed ratings of the instrument.
- Apply power to the circuit being measured.
- The value of the current being measured is indicated on the

Operation

numerical display. The analog display can be used for nulling or peaking applications.

- Remove all power from the circuit being measured and discharge all capacitors.
- Disconnect the test leads and reconnect the circuit which was originally opened.

4.5 AC CURRENT MEASUREMENTS

- Review Safety Precautions in Paragraph 4.2.
- Depress ACmA function switch.
- Depress the appropriate current range switch as indicated in Table 4-5. If the current being measured is unknown (but less than 10A), begin with the 20(10A) switch. Connect the red test lead to the 10A jack and the black test lead to the COMMON jack.

Table 4-5. AC Current Ranges and Connections

Range	Range Switch	Function Switch	Input Connections	Max. Current Amperes	Range
0 to $200\mu\text{A}$	200 μA	ACmA	mA, COMMON	2.5	<p>50 Hz to 20 kHz on all ranges</p>
0 to 2mA	2	ACmA	mA, COMMON	2.5	
0 to 20mA	20 10 A	ACmA	mA, COMMON	2.5	
0 to 200mA	200	ACmA	mA, COMMON	2.5	
0 to 2000mA	2000	ACmA	mA, COMMON	2.5	
0 to 10A	20 10A	ACmA	10A, COMMON	10	

- d. Remove all power to the circuit being measured and discharge all capacitors.
- e. Connect the test leads according to Table 5-1.
- f. Open the circuit in which the current is to be measured and securely connect the test leads in series. Insure that the 480-3 is not connected across a voltage source which can exceed ratings of the instrument.
- g. Apply power to the circuit being measured.
- h. The value of the current being measured is indicated on the numerical display. The analog display can be used for nulling or peaking applications.
- i. Remove all power from the circuit being measured and discharge all capacitors.
- j. Disconnect the test leads and reconnect the circuit which was originally opened.

SECTION V THEORY OF OPERATION

5.1 GENERAL

5.1.1 This section describes the theory of operation of the Simpson 480. All modes of operation are described first, then, description of the circuits follows.

5.2 OVERALL SYSTEM

5.2.1 The basic system block diagram for the 480 is shown in Figure 5-1.

5.2.2 Signal Conditioning Section

5.2.2.1 The parameter being measured is connected to the appropriate input terminals. The corresponding Signal Conditioning circuits convert this parameter into a proportional DC voltage. The conversion is accomplished by the Attenuator, Current Shunts, Resistance Converter, AC-to-DC Converter, and associated switching.

5-1

Theory of Operation




Figure 5-1. Basic System Block Diagram, 480-3

OBSOLETE

5.2.6 Analog-To-Digital Converter Section

5.2.6 The Analog-To-Digital (A/D) Converter section changes the DC output voltage from the Signal Conditioning section to digital information. The A/D Converter also provides a proportional analog signal for the Analog Display.

5.2.7 Display Section

5.2.8 Through the Segment and Anode Drivers, the digital information from the A/D Converter is indicated on the 7-segment Numerical Display. The proportional analog signal is indicated by the Analog Display.

5.3 INPUT CIRCUITS

5.3.1 DC Voltage Measurements

- The basic DC voltage measurement circuit is shown in Figure 5-2, (a). The DC voltage being measured is connected to the V-Ω and COMMON jacks, attenuated according to the range selected and converted into digital information by the A/D Converter.
- The A/D Converter circuit provides two basic full range sensitivities: 200mV and 2V. This feature simplifies the attenuator design. No attenuation is required on the 200mV and 2V ranges. The same attenuator ratio is used on the 20V and 200V ranges. A separate attenuator tap is provided for the 1000 volt range.

5.3.2 AC Voltage Measurements

- The basic AC voltage measurement circuit is shown in Figure 5-2, (b).
- The AC voltage being measured is connected to the V-Ω and COMMON jacks, attenuated according to the range selected, and applied to an Input Amplifier. The output of the amplifier is converted into DC by an AC to DC Converter, and the resulting DC voltage is measured by the A/D Converter.
- The attenuator is not used on the 200mV and 2V ranges. On the


higher ranges, the attenuator is frequency-compensated to provide accurate readings over a wide frequency range.

- The Input Amplifier achieves a high input impedance and presents a low output impedance to the converter.
- The AC to DC Converter uses a half-wave operational amplifier-rectifier circuit which provides two basic full range sensitivities: 200mV and 2V. It is average-responding, but its calibration (gain) is based on the rms value of a sine wave.



(A) DC VOLTAGE

OBSOLETE



(B) AC VOLTAGE

Figure 5-2. Basic Voltage Measurement Circuits

Theory of Operation

- The output of the Operational Amplifier has two rectifying diodes and two feedback resistors, R_1 and R_2 . These components drive a summing resistor R_3 . The junction of the summing resistor and feedback resistors is connected to the amplifier input to provide negative feedback. With a sine-wave input signal, the positive half cycles of the output waveform go through one diode, and the negative half cycles through the other diode. The positive half cycle is filtered and the resulting DC voltage is measured by the A/D Converter.

- The indications of the numerical display are calibrated to the one sine wave value being measured.

5.3.3 AC Current Measurements

5.3.4 The basic AC current measurement circuit is essentially the same as the DC current measurement circuit (refer to 5.3.5), except that the voltage developed across the internal shunt resistance is measured by the AC voltage measurement circuit.

5.3.5 DC Current Measurements

- The basic DC current measurement circuit is shown in Figure 5-3, (a).
- The current being measured is connected in series with the COM/COMMON and the mA (or 10A) jacks and an internal precision shunt resistor. The value of the shunt resistance depends on the current range used and is selected so that the voltage developed across it is proportional and numerically equal to the current through it. The A/D Converter measures this voltage, and the value indicated on the numerical display is equal to the current being measured.
- The full range sensitivity of the digital voltmeter circuit measurement is 200mV . Therefore, the internal resistance for each current range equals 200mV divided by the full range current. For example, if the full range current is 20mA , then the internal resistance would be 1000 ohms.

Theory of Operation



(A) DC CURRENT



(B) RESISTANCE

Figure 5-3. Basic DC Current and Resistance Measurement Circuits

5.3.5 Resistance Measurements

- The basic resistance circuit is shown in Figure 5-3, (b).
- The resistance being measured, R_x , is connected to the V- Ω and COM/COMMON jacks and a constant current is applied through it by the instrument. The resulting voltage is proportional to the value of R_x . The value of the current is determined by the resistance of the range selected.
- The current through R_x is controlled by an Operational Amplifier whose inputs "follow" R_x and the output is always $R_x + R_r$ (where R_r is a reference voltage). This reference voltage is

Theory of Operation

developed by the current from a constant current source through a feedback resistor.

- The $I_{s1} + I_{s2}$ output of the amplifier maintains a constant current through R_x , regardless of the value of R_x . The magnitude of the current is determined by the resistance (precision resistors selected by the ohms range switch) in series with R_x .
- The A/D Converter measures the voltage developed across R_x , and the value indicated on the numerical display is equal to the resistance of R_x .
- When the instrument is set for LO OHMS measurements, the full scale voltage across R_x is set to 300 mV. The maximum open circuit voltage for this function is 1 volt. This condition is accomplished by the "ON" state of the Active Voltage Clamp.
- When the instrument is set for HI OHMS measurements, the full scale voltage across R_x is set to 2 volts. The maximum open circuit voltage for this function is 7 volts.

3.4 A/D CONVERTER

3.4.1 The basic block diagram of the A/D Converter is shown in Figure 3-4. The circuit utilizes the "Up-Down" integration technique for the analog-to-digital conversion. This technique is based on the conversion of a DC voltage into a proportional time period. The converter initially accumulates a charge proportional to the input signal on an integrating capacitor for a fixed period of time. In the second integration period, the capacitor discharges back to the "zero" voltage starting point, when the input signal is removed and a reference voltage opposite in polarity is placed at the input of the converter. The ratio of the time required to remove the integrator charge to the initial fixed time period is proportional to the amplitude of the input DC voltage.

3.4.2 The "Up-Down" A/D Converter requires two periods of integration for each measurement. The input signal (I_{in}) is integrated on the "up" slope during the first period; the reference voltage is integrated on the "down" slope of the second period. The

Theory of Operation



OBsolete

Figure 3-4. A/D Converter Block Diagram

first period starts with a pulse initiated by the Sample & Hold Oscillator which generates four pulses per second as shown in (1) of the Basic Timing Diagram (Figure 3-5).

3.4.3 The pulse resets the Decode Counter to "zero" and the trailing edge of the pulse initiates the first period T_1 . During T_1 , the DC voltage I_{in} is sampled, and the integrator generates a ramp whose slope is proportional to the value of the input signal. Also during T_1 , the Master Oscillator (2) produces pulses which are counted by the Decode Counter until a total of 1,000 counts is accumulated. At this moment, period T_1 ends and T_2 begins.

Theory of Operation




Figure 5-6. Basic Timing Diagram

5.4.4 During T_1 , the input signal is removed, and a reference voltage of the opposite polarity is connected to the Integrator input. The Integrator at this time produces a ramp toward the starting point with a fixed slope as shown in (B) of the timing diagram. When the Integrator output has reached the "zero" voltage starting point, the Zero Detector changes state. At this point the reference voltage is removed and the Control Logic inhibits the Master Oscillator.

5.4.5 The count stored in the Decade Counter is in turn transferred to the Latches via a strobe pulse (S) generated by the Control Logic. The BCD information is then multiplied, divided into

Theory of Operation

7-segment information, and externally displayed through the Segment and Anode Drivers.

5.4.6 The other requirements of the AD Converter such as overrange and polarity indications are accomplished by the Control Logic and Counter Circuits.

5.5 POWER SUPPLY CIRCUITS

OBSELETE

5.5.1 AC Line Power

- The AC line power supply is shown in Figure 7-1, Schematic Diagram. The incoming AC power is applied to the primary power transformer T_1 . The primary winding is tapped for 200 VAC, 220 VAC and 120 VAC operation. The secondary windings generate step-down voltages to provide 3 regulated DC voltages.
- Regulated DC voltages of +12V and -12V are produced by two full-wave rectifiers, followed by two series-type voltage regulators. These regulated voltages are used to supply power to the analog circuits.
- A full-wave rectifier, followed by IC12, provides a regulated +5V supply to all digital integrated circuits and the LED display. An unregulated +10V supply is generated for operating the Resistance Converter.

5.5.2 Battery Power (466D only)

- The battery-operated power supply of the 466D is shown on Figure 7-1, Schematic Diagram. With the POWER switch ON, the battery is connected to the input of the DC-To-DC converter consisting essentially of T201 and transistors Q101 and Q102 in a multi-transistor configuration. The multi-transistor signal is coupled by T201 to the bridge rectifier and regulators to generate DC voltages of +12V, -12V, and +5V. The required +1 volt supply is provided by the battery.
- The battery is charging whenever the 466D is connected to the AC line. A secondary winding from Transformer T_1 , and the associated rectifier provides power to operate a constant

current source for charging the battery. The constant current source, consisting essentially of Z204 and Q28, provides a charging current of approximately 400 milliamperes when the instrument is OFF. Approximately 50 milliamperes is supplied to charge the battery when the instrument's POWER switch is set to ON.

- c. When the 460D is operated with AC line power (no battery power) the battery-charging constant current source provides the +5V supply required for operation.

OBSOLETE

WARNING

These servicing instructions are for use by qualified personnel only. To avoid electrical shock, do not perform any servicing other than that contained in the operating instructions unless you are qualified to do so.

SECTION VI

SERVICING INSTRUCTIONS

6.1 GENERAL

6.1.1 The Simpson 460 is carefully designed and constructed with high quality components. By providing reasonable care and following the instructions in this manual, the user can expect a long, useful service life from his instrument.

6.2 COVER REMOVAL

The battery cover can be removed for maintenance purposes by the following procedure:

WARNING

Remove all power and connections to the instrument before removing the case cover. Do not operate the instrument with the bottom cover removed.

- Depress the POWER switch to the OFF position.
- Disconnect the line cord from the power source and all connections from the instrument.
- Pull out the knobs on sides of instrument and raise the handle towards the rear of instrument.
- Turn the instrument over and remove the four screws in the rubber feet.
- Lift bottom cover and remove handle.
- Reverse this procedure when replacing the cover.

6.3 BATTERY INSTALLATION (460D only)

NOTE: Refer to Table F-1 for recommended batteries.

CAUTION **OBSOLETE**

To avoid dangers associated with recharging batteries, use only the type specified in Table F-1. Do not attempt to use cadmium zinc, alkaline or the like that is not designed to be recharged.

- Remove bottom cover (refer to paragraph 6.2). Remove the retaining tablings from the battery holder. Insert two-cell in into each retainer. Then install the combination into the holder. Insure that the cells are installed according to the polarity orientation designated on the battery holder label. *Failure to do so can damage the 460D.*
- Check that the battery contacts are clean and making good connection.
- Replace the bottom cover.
- For battery recharging, refer to paragraph 6.4, below.
- Test the battery according to paragraph 4.3.2.

6.4 BATTERY CHARGING (Model 460D only)

- The battery is being charged at full rate when the POWER switch is set to the OFF position and AC power is applied to the instrument. Approximately 16 hours are required to fully charge the battery in this mode of operation.

NOTE: If the battery voltage checks below 14.7 volts, charge the battery with the POWER switch set to OFF for at least 15 minutes before operating the instrument.

- The battery is being "trickle" charged whenever the instrument is operated by the AC power line.

6.5 BATTERY CARE

- Avoid discharging the cells completely. Check the battery voltage periodically using the BATTERY TEST jack (refer to paragraph 4.3.2). Charge the battery whenever the voltage is close to or below +4.7 Volts.
- Do not operate the Instrument with discharged cells. Make sure to recharge all newly purchased batteries (refer to 6.5, step a) for at least 15 minutes before operating the Instrument.
- Whenever the line-card is not connected and the Instrument is not in use, remember to set the POWER switch to the OFF position.
- With nickel-cadmium cells installed in the 480L, avoid storing in an area where the temperature exceeds +50°C.

6.6 FUSE REPLACEMENT

6.6.1 The line and current fuses are mounted inside fuse holders on the main P.C. Board as shown in Figure 6-1. Use the following procedure to replace a fuse.

WARNING

Remove all power and input connections to the Instrument before removing bottom cover. Do NOT replace a blown fuse with a fuse which has a larger rating or slower time lag characteristics than those specified.

- Remove bottom cover as described in paragraph 6.2.




Figure 6-1. Fuse Location, 480-L

- Carefully lift the defective fuse from the holder and replace with appropriate fuse (refer to Table 7-3).
- Replace the bottom cover.

6.7 PREVENTIVE MAINTENANCE

6.7.1 Daily Care

WARNING

Do not attempt to clean this Instrument with the test leads connected to a power source or when it is connected to the AC power line.

Service Instructions

- Immediately clean all spilled materials from the instrument and wipe dry. If necessary, moisten a cloth with soap and water to clean plastic surfaces.
- Do not allow the battery to fully discharge. A completely discharged battery generally becomes inactive and a replacement will be necessary. Check the battery voltage according to paragraph 4.3.2.
- Whenever possible, avoid exposure or usage in areas which are subject to temperature and humidity exposures, vibration or mechanical shock, dust or corrosive fumes, or strong electrical or electromagnetic interferences.

6.7.2 Monthly Care

Verify instrument calibration by performing operational checks using known values/sources. If the need for calibration is indicated, contact your nearest Authorized Simpson Service Center.

6.7.3 Annual Care

It is recommended that the instrument be returned annually to a Simpson Authorized Service Center or the factory for a complete overall check and calibration.

6.7.4 Storage

When the instrument is not in use, store it in a location free from temperature extremes, dust and corrosive fumes, and mechanical vibration or shock.

6.8 TROUBLESHOOTING

6.8.1 If the instrument does not yield satisfactory results, follow this procedure, before attempting maintenance on the instrument.

- Review and comply with the Preliminary Notes and Checks, listed in paragraph 4.3.
- Check that all switches are positioned correctly for the parameter and range of value being measured and that the measurement situation is within the ratings of the instrument.

Service Instructions

- If the 480D has been operated with battery power, be sure that the cells are charged and properly installed (refer to paragraph 4.3).
- If the 480D has been operated with AC power insure that power source is within the instrument specifications, and free from excessive fluctuations and transients.
- Insure that the environment in which the instrument is being used is within the instrument specifications.
- Inspect the device being measured and the measurement test set-up to insure that proper shielding and grounding techniques have been used. Also consider whether the instrument is significantly affecting the circuit being measured.

6.8.2 If the steps taken in paragraph 6.8.1 do not yield satisfaction refer to the troubleshooting chart (Table 6-1). Direct all other repair and adjustment needs to a Simpson Authorized Service Center.

OBSOLETE

Table 6-1. Troubleshooting Chart

Symptom	Possible Causes	Case
1. No indication on numerical display when 480D is battery operated, AC operation is OK.	Cells — Discharged, defective, not installed properly, making poor contact, or missing.	Check battery voltage. Refer to para. 4.3.2. If OK contact nearest Simpson Authorized Service Center.
2. LOW intensity on numerical display in battery operation. (480D).	Cells not fully charged.	Check battery voltage. Refer to para. 4.3.2. If battery checks low, remove cover and check that the cells are installed correctly and making good contact. Refer to 4.3. If they are,

Service Instructions

Symptom	Probable Causes	Cure
1. No indication on the numerical display when instrument is AC line operated (no cells installed).	a. Low or no voltage at power source receptacle. b. Line cord disconnected. c. Defective line cord. d. Line fuse open.	replace cover and charge battery overnight. Refer to para. 4.1. a. Restore correct voltage at power receptacle. b. Connect line cord. c. Repair or replace cord. d. Replace line fuse. Refer to 4.1.
4. Batteries do not respond to charge, meter operation OK when connected to AC power.	Cells defective, not installed properly, making poor contact, or mixing.	Remove cover and check that cells are installed correctly and making good contact. Refer to 4.1. If they are, check the voltages of the individual cells. Replace those which check significantly lower than normal (1.25 volts).
5. Operation normal on all functions and ranges except AC and DC Current.	Current fuse F2 open.	Replace fuse to 4-5
6. Indications fluctuate and/or drift, even though indication is OK at 500 with the input terminals shorted, and at 5000 ohms when using a stable and low impedance input.	Fluctuations and/or drift are being generated by the device being measured or the measurement test set up.	Use proper shielding, grounding techniques and connections to minimize "pick-up" of unwanted signals due to ground loops, poor connections, and capacitive and/or inductive coupling. Op-

Service Instructions

Symptom Probable Causes Cure

OBsolete

7. Indication is OK on battery. However, on AC operation, the reading fluctuates and/or drifts at 5, with the input shorted, and/or at 5000 ohms using a stable and low impedance input. (4000)	AC power source is low or fluctuating (including transients).	Connect the power source or use instrument on battery.
8. Same as 7 above, except indication OK on AC but not battery operation.	a. Battery voltage low. b. One or more cells defective, not installed correctly.	a. Check battery condition. Refer to para. 4.1.2. If not OK, charge battery, refer to para. 4.1. b. Remove cover and check that cells are installed correctly and making good contact. If OK, replace all cells temporarily with conventional carbon

rate instrument (meter only) on battery for complete isolation from the power line.

NOTE: If the drift and/or fluctuation is coming from the device being measured, no cure is required, the measurement is valid, and the device must be corrected.

Service Instructions

Symptom	Probable Cause	Cure
		also "D" size cells for checking purposes only. If problem still exists, contact nearest Simpson Authorized Service Center.
8. Slow response. Operation OK when using a low impedance input.	Parameter being measured/has high source impedance.	None required.
10. Accuracy not within specifications when checked with a stable, higher accuracy (at least 5 times better) low impedance (voltage measurements) source.	a. Instrument is out of calibration. b. Instrument not stored properly.	Contact nearest Simpson Authorized Service Center.
11. Accuracy of instrument is within specifications but measurements appears in error.	a. Instrument affects circuit being measured. b. Common and/or normal mode specifications is being exceeded.	a. Study circuit being measured vs. instrument specifications. Correct indications accordingly. b. Refer to cure in Item 8 above.

SECTION VII

Replacement Parts, Schematic Diagram, and Authorized Service Centers

OBSOLETE

Table 7-1. Replacement Parts List

Reference Symbol	Description	Part No.
[= Parts used on 455A only	
	= Parts used on 4602 only	
All other parts are common to both instruments		
	*Battery, "D" size, 1.5V, 4-Ampere-Hrs., Nickel-Cadmium, Eveready Type GM-Rentagable, or Equal	
	Bracket, Assembly, Power, Converter	18-060210
	Board, PC Assembly, DC Converter	18-060230
	Board, PC Assembly, Resistor	18-060231
	Board, Printed Circuit, Main	18-060214
	Bracket, Resistor	9-104903

*Available at local electronic parts distributors

Replacement Parts

	Batten, Black	9-158378
	Batten, Gray	9-158388
	Batten, Red	9-158379
	Cable, Ribbon, 10 Conductor	9-158419
	Case Assembly, Top	10-983217
	Case Assembly, Bottom	9-158375
	Clp. Face, PC Mounting	9-157730
	Handle, Milled	9-158375
	Handle, Insert	9-158390
	Holder, Battery	9-158390
	Panel, Assembly	10-983217
	Rubber Feet	9-157820
	Shield, Amplifier, AC	9-158093
	Spacer, Hex	9-528437
	Screw, Rubber Foot	9-149372
	Switch, Pushbutton, 10 Station	9-158900
C-1	Capacitor, 3.3 μ F, $\pm 5\%$, 15V C.O.	9-157138
C1	Capacitor, 200 μ F, $\pm 5\%$, 200V, Poly.	9-158400
C1	Capacitor, 270 μ F, $\pm 5\%$, 200V, Poly.	9-158900
C4, C3	Capacitor, Variable, 0.5 -40 μ F, 100V	9-158235
C5	Capacitor, 400 μ F, $\pm 20\%$, 500V	9-157732
C7, C10	Capacitor, 400 μ F, $\pm 20\%$, 500V	9-158350
C8, C12	Capacitor, 100 μ F, $\pm 10\%$, 500V	9-158022
C8	Capacitor, 5 μ F, $\pm 10\%$, 100V	9-158022
C10, 11, 12, 14, 24, 26, 30, 34	Capacitor, 51 μ F, $\pm 10\%$, 50V	9-158315
C13, 28, 23, 27, 29, 31, 35, 36	Capacitor, 33 μ F, 16V, Tantalum	9-155324
C16	Capacitor, 301 μ F, 15V	9-157119
C17	Capacitor, 5 μ F, ± 10 - $\pm 50\%$, 10V	9-158650
C18	Capacitor, 3 μ F, $\pm 10\%$, 500V	9-158350
C19	Capacitor, 100 μ F, 50V, Tantalum	9-157338
C21	Capacitor, 82 μ F, $\pm 10\%$, 200V, Mica	9-158387
C25	Capacitor, 5 μ F, ± 5 μ F, 100V, Mica	9-155330
C28	Capacitor, 20 μ F, $\pm 20\%$, 100V, C.O.	9-158280
C30	Capacitor, 47 μ F, 10V, Tantalum	9-155330

OBSOLETE

Replacement Parts

(C36, 37)	Capacitor, 470 μ F, 15V, Electro.	9-158408
C38	Capacitor, 2200 μ F, 10V, Electro.	9-159094
D1-D6, D13-D17	Diode, Silicon, 70 PIV, 70 MA, 100V4	9-152004
D6, D28	Diode, Silicon, Low Leakage, 100V19	9-158988
D11, D12	Diode, Silicon, 70 PIV, 70 MA, Std. 100V4	9-157179
D19-C21	Diode, Silicon, 200 PIV, 2.5A, 100V20	9-158328
(D22, 26, 27)	Diode, Silicon, 200 PIV, 1A, 100V1	9-154600
(D23, 28 29)	Diode, Silicon, 200 PIV, 1A, 100V1	9-154600
F1	Fuse, 150 VAC, Operation, Slow Blow	9-158320
F2	Fuse, 140 VAC, Operation, Slow Blow	1-195184
	Fuse, 2.5A, 125V, Normal Blow	9-158887
Q1, 2, 4, 5, 18, 21, 23	Transistor, Silicon, MPN 2N7331	9-155324
Q3, 5, Q7-Q10, Q18, 20, 22, 25, 26, 27	Transistor, Silicon, PNP 18F5070	9-155864
Q17	Transistor, PFT, N-Channel, 2N5088	9-157247
Q19	Transistor, Silicon, PNP, 8V4201	9-155864
Q20	Transistor, Silicon, MPN 2N7330	9-155320
(Q28)	Transistor, Silicon, MPN 2N670	9-155864
	Resistor, Std. Standard, $\pm 10\%$,	
R1	10.0K Ω , $\pm 10\%$, 1W	
R2	80.0K Ω , $\pm 10\%$, 1W	9-158887
R3	9.90 Meg Ω , $\pm 10\%$, 1W	
R4	Resistor, 470K Ω , $\pm 10\%$, 2W	9-158443
R5, 6, 8, 13	Resistor, 100K Ω , $\pm 1\%$, 5W	9-155320
R7	Pat. 100K Ω , $\pm 10\%$, 5W, Carbon	9-158908
R8, R11	Resistor, 200K Ω , $\pm 1\%$, 10W	9-157655
R20	Pat. 50K Ω , $\pm 10\%$, 5W, Carbon	9-158908
R21	Resistor, 500 Ω , $\pm 10\%$, 5W	9-154750
R22	Pat. 50K Ω , $\pm 10\%$, 5W, Carbon	9-158908
R24	Resistor, 100 Ω , $\pm 1\%$, 5W	9-158908

OBSOLETE

Replacement Parts

R16, R7, R8, R9, R9, R2, R7, R8, R1, R5, R9	Resistor, 10kΩ, ±10%, 1/4W	5-110814
R18, R79	Resistor, 27kΩ, ±5%, 1/4W	5-110890
R21	Resistor, 9.0kΩ, ±5%, 1/4W	5-110902
R22, R1, R4, R7	Resistor, 10.0kΩ, ±5%, 1/4W	5-110903
R23	Resistor, 10kΩ, ±5%, 1/4W	5-110970
R24	Resistor, 47.5kΩ, ±5%, 1/4W	5-110981
R25	Resistor, 20.7kΩ, ±5%, 1/4W	5-110985
R26, R39	Pot. 5kΩ, ±20%, 1/2W, Control 25 Turn	5-110923
R27	Resistor, 4.0kΩ, ±5%, 1/4W	5-110983
R28, R31	Resistor, 6.8kΩ, ±5%, 1/4W	5-110976
R29, R38	Resistor, 6.8kΩ, ±5%, 1/4W	5-117680
R31, R2, R7	Pot. 5kΩ, ±20%, 1/2W, Control	5-110979
R33	Resistor, 4.7kΩ, ±5%, 1/4W	5-110973
R34	Resistor, 4.0kΩ, ±5%, 1/4W	5-117680
R35	Resistor, 10kΩ, ±5%, 1/4W	5-110970
R36	Resistor, 27kΩ, ±5%, 1/4W	5-110970
R37	Resistor, 15kΩ, ±10%, 1/4W	5-110923
R40	Resistor, 10kΩ, ±5%, 1/4W	5-110980
R41	Resistor, 9.0kΩ, ±5%, 1/4W	5-110976
R42	Resistor, 90.0kΩ, ±5%, 1/4W	5-110977
R43	Resistor, 9.0kΩ, ±5%, 1/4W	5-110976
R44	Resistor, 11kΩ, ±5%, 1/4W	5-110920
R45, R31	Resistor, 22kΩ, ±10%, 1/4W	5-117180
R46, R2, R8, R9, R9, R9	Resistor, 1kΩ, ±5%, 1/4W	5-110873
R47, R8, R9, R9	Resistor, 10kΩ, ±10%, 1/4W	5-110924
R49	Resistor, 1.5kΩ, ±10%, 1/4W	5-110873
R51, R1, R2, R2	Resistor, 470kΩ, ±10%, 1/4W	5-110900
R53	Pot. 5kΩ, ±20%, 1/2W, Control	5-110900
R54	Resistor, 27.5kΩ, ±10%, 1/4W	5-110418
R55, R19	Resistor, 25.5kΩ, ±5%, 1/4W	5-110942

OBSOLETE

Replacement Parts

R56, R79	Resistor, 10kΩ, ±5%, 1/4W	5-110412
R58, R9, R9, R9, R9, R9	Resistor, 5kΩ, ±5%, 1/4W	5-110418
R60	Resistor, 47kΩ, ±5%, 1/4W, C.C.	5-110907
R62, R64	Resistor, 10kΩ, ±5%, 1/4W	5-110412
R68	Resistor, 17.5kΩ, ±5%, 1/4W	5-110400
R69, R70	Resistor, 2.0kΩ, ±5%, 1/4W	5-110400
R71, R4	Resistor, 10kΩ, 1/4W	5-110402
R72	Pot. 10kΩ, ±20%, 1/2W, Control	5-110404
R73	Resistor, 5kΩ, ±5%, 1/4W	5-110924
R77	Resistor, 100kΩ, ±10%, 1/4W	5-110408
R84, R82	Resistor, 8.2kΩ, ±10%, 1/4W	5-110977
R89	Resistor, 1.0kΩ, ±5%, 1/4W	5-110942
R90	Resistor, 15.0kΩ, ±5%, 1/4W	5-117620
R90	Resistor, 10kΩ, ±5%, 1/4W	5-117620
R91	Resistor, Network, 10kΩ	5-110920
R92	Resistor, Network, 5kΩ	5-110410
T1	Transformer, Power	5-110416
Z1	I.C., Op. Amp., LF158A	5-110900
Z2, Z10	I.C., Op. Amp., LM3090A	5-110900
Z3	I.C., Op. Amp., LM3091AN	5-110945
Z4	I.C., Op. Amp., 740	5-110920
Z5, R, 12	I.C., Dual Op. Amp., LM1495	5-117622
Z6	I.C., Quad Interval Switch	5-110900
Z7	I.C., A/D Digital 160	5-110944
Z8	I.C., Op. Amp., 708	5-110942
ZC12	I.C., ±5V, Voltage Regulator	5-117620
ZD1, ZD2	Diode, Zener, 3.3V, ±5%, 500 MW, 1N751A	5-110907
ZD3	Diode, Zener, 6.4V, ±5%, 500 MW, 1N4570	5-110923

OBSOLETE

ALLEN TELE. AND COMM. CORP.

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUMINUM PRODUCTS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

ALUM. PANELS, CHARLOTTE 1985

12000 W. 10th Ave.
Denver, CO 80202
Tel. 303-751-1700

NEW SIMPSON



SERIES 2850 DIGITAL PANEL METER

- 0.5% precision gas discharge display
- Model 2850 100 mA
- 0.5% LED display Model 2851
- and 100V
- 1/2" high resolution
- Automatic zero reset polarity
- 0.1% of reading accuracy
- 500V output for overload
- Front/Inch edge connector included
- Shunt/relay built-in circuitry
- Storage of circuit data, readable in 0.1 volt operation

Model 2850 100 mA 0.5% precision gas discharge display, complete with panel mounting slips, edge connector and manual.

Model 2851 100V input, 0.5% precision gas discharge display, complete with panel mounting slips, edge connector and manual.

Model 2852 100mA 100V input, 0.5% LED display, complete with panel mounting slips, edge connector and manual.

Model 2853 100V input, 0.5% LED display, complete with panel mounting slips, edge connector and manual.

NOW... a single DPM for popular domestic and IEC/CEM circuits



1 Dealer, Best Delivery
11 0PM Delivery

